

## Huron County Soil Summary Sheet

Map Symbol	Soil Series and Surface Texture	Natural Drainage	Hydrologic Group	Erosion Factor	POTENTIAL FOR	
					Wind Erosion	Soil Compaction
B.L.	Bottom Land	VARIABLE	-	-	-	-
Bc	Brookston Clay Loam	POOR	VERY SLOW	3	4	H
Bes	Berrien Sandy Loam	IMPERFECT	SLOW	3	2	M
Bg	Burford Loam	WELL	RAPID	4	2	L
Bos	Bookton Sandy Loam	WELL	MODERATE	4	2	L
Brl	Brisbane Loam	IMPERFECT	MODERATE	2	3	M
Brs	Brady Sandy Loam	IMPERFECT	MODERATE	4	2	M
Bs	Brookston Silt Loam	POOR	VERY SLOW	3	3	H
Bsc	Brookston Silty Clay Loam	POOR	VERY SLOW	3	4	H
DI	Dumfries Loam	WELL	RAPID	4	2	L
Dos	Donneybrook Sandy loam	WELL	RAPID	4	1	L
Ds	Dumfries Sandy Loam	WELL	RAPID	4	1	L
Fs	Fox Sandy Loam	WELL	RAPID	4	1	L
Gil	Gilford Loam	POOR	SLOW	3	3	H
Gs	Granby Sandy Loam	POOR	SLOW	4	2	M
Gul	Guerin Loam	IMPERFECT	MODERATE	2	3	M
HI	Harriston Loam	WELL	MODERATE	1	3	L
Hs	Harriston Silt Loam	WELL	MODERATE	1	3	L
Huc	Huron Clay Loam	WELL	SLOW	2	4	M
Hus	Huron Silt Loam	WELL	SLOW	2	4	L
LI	Listowel Loam	IMPERFECT	MODERATE	2	3	M
Ls	Listowel Silt Loam	IMPERFECT	MODERATE	2	3	M
Lyl	Lyons Loam	POOR	SLOW	3	3	H
M	Muck	VERY POOR	SLOW	3	2	M
Pal	Parkhill Loam	POOR	SLOW	2	3	H
Pas	Parkhill Silt Loam	POOR	SLOW	2	3	H
Pc	Perth Clay Loam	IMPERFECT	SLOW	3	3	H
Ps	Perth Silt Loam	IMPERFECT	SLOW	2	4	M
Psc	Perth Silty Clay Loam	IMPERFECT	SLOW	3	3	H
Tc	Toledo Clay Loam	POOR	VERY SLOW	3	4	H
Tes	Teeswater Silt Loam	WELL	MODERATE	4	2	L
Ts	Toledo Silt Loam	POOR	VERY SLOW	3	3	H
Was	Wauseon Sandy Loam	POOR	SLOW	4	3	M