

Lennox and Addington County Soil Summary Sheet

Map Symbol	Soil Series and Surface Texture	Natural Drainage	Hydrologic Group	Erosion Factor	POTENTIAL FOR	
					Wind Erosion	Soil Compaction
Basl	Bancroft Sandy Loam	WELL	RAPID	4	1	L
Bes	Berrien Sandy Loam	IMPERFECT	SLOW	3	2	M
Bl	Bondhead Loam	WELL	MODERATE	1	3	L
Bl-sh	Bondhead Loam - Shallow Phase	WELL	RAPID	1	4	L
Bos	Bookton Sandy Loam	WELL	MODERATE	4	2	L
Bsl	Bondhead Sandy Loam	WELL	MODERATE	4	1	L
Bsl-sh	Bondhead Sandy Loam - Shallow Phase	WELL	RAPID	3	2	L
Cs	Cramahe Gravelly Loam	WELL	RAPID	4	2	L
DI	Dummer Loam	WELL	MODERATE	1	3	L
DI-sh	Dummer Loam - Shallow Phase	WELL	RAPID	1	4	L
Ec	Elmbrook Clay	IMPERFECT	SLOW	3	4	H
EI	Emily Loam	IMPERFECT	MODERATE	2	3	M
EI-sh	Emily Loam - Shallow Phase	IMPERFECT	RAPID	2	4	M
FI	Farmington Loam	WELL	MODERATE	1	4	L
Gc	Gananoque Clay	WELL	SLOW	3	3	M
Grsl	Granby Sandy Loam	POOR	SLOW	4	2	M
Gul	Guerin Loam	IMPERFECT	MODERATE	2	3	M
Gul-sh	Guerin Loam - Shallow Phase	IMPERFECT	RAPID	2	4	M
Hsil	Hinchinbrooke Silt Loam	POOR	SLOW	2	3	H
Lac	Lansdowne Clay	IMPERFECT	VERY SLOW	3	4	H
Lac-sh	Lansdowne Clay - Shallow Phase	IMPERFECT	SLOW	2	4	H
Lc	Lindsay Clay	POOR	VERY SLOW	3	3	H
Lc-sh	Lindsay Clay - Shallow Phase	POOR	SLOW	2	3	H
Lyl	Lyons Loam	POOR	SLOW	2	3	H
Lyl-sh	Lyons Loam - Shallow Phase	POOR	MODERATE	3	3	H
M	Muck	VERY POOR	SLOW	3	2	M
Ma	Marsh	VERY POOR	-	-	-	-
Mc	Moscow Clay	POOR	VERY SLOW	3	3	H
Mc-R	Moscow Clay - Rocky Phase	POOR	VERY SLOW	3	3	H
Ms-sh	Moscow Clay - Shallow Phase	POOR	SLOW	2	3	H
Msl	Monteagle Sandy Loam	WELL	MODERATE	4	1	L
Nc	Napanee Clay	POOR	VERY SLOW	3	3	H
Nc-sh	Napanee Clay - Shallow Phase	POOR	SLOW	2	3	H
Nufsl	Newburg Fine Sandy Loam	WELL	MODERATE	1	3	L
OI	Otonabee Loam	WELL	MODERATE	1	3	L
OI-s	Otonabee Loam - Steep Phase	WELL	MODERATE	1	3	L
OI-sh	Otonabee Loam - Shallow Phase	WELL	RAPID	1	4	L
OI-st	Otonabee Loam - Stony Phase	WELL	RAPID	1	3	L
P	Peat	VERY POOR	SLOW	3	2	M

Map Symbol	Soil Series and Surface Texture	Natural Drainage	Hydrologic Group	Erosion Factor	Wind Erosion	Soil Compaction
PI	Picadilly Loam	IMPERFECT	VERY SLOW	2	3	M
RL	Rockland	-	-	-	-	-
RO	Rock Outcrop	-	-	-	-	-
Sc	Sidney Clay	POOR	VERY SLOW	3	3	H
Sc-sh	Sidney Clay - Shallow Phase	POOR	SLOW	2	3	H
SI		WELL	RAPID	4	1	L
Soc	Solmesville Clay	IMPERFECT	SLOW	3	3	H
SPg	St. Peters Gravelly Sandy Loam	WELL	RAPID	4	1	L
Tis	Tioga Sandy Loam	WELL	RAPID	4	1	L
WLs	White Lake Gravelly Sandy Loam	WELL	RAPID	4	1	L
Was	Wauseon Sandy Loam	POOR	SLOW	4	3	M
Wcl	Waupoos Clay Loam	WELL	SLOW	3	3	M
Wes	Wendigo Loamy Sand	WELL	RAPID	4	1	L
Wes-R	Wendigo Loamy Sand - Rocky Phase	WELL	RAPID	4	1	L