## **Prescott County Soil Summary Sheet**

|               | 1 10000tt Gounty Gon Guinnary Gneet    |                     |                     |                   | <b>POTENTIAL FOR</b> |                    |  |
|---------------|----------------------------------------|---------------------|---------------------|-------------------|----------------------|--------------------|--|
| Map<br>Symbol | Soil Series and Surface Texture        | Natural<br>Drainage | Hydrologic<br>Group | Erosion<br>Factor | Wind<br>Erosion      | Soil<br>Compaction |  |
| Afsl          | Allendale Fine Sandy Loam              | POOR                | SLOW                | 3                 | 3                    | Н                  |  |
| B.L.          | Bottom Land                            | VARIABLE            | -                   | -                 | -                    | -                  |  |
| Вс            | Bearbrook Clay                         | POOR                | VERY SLOW           | 3                 | 3                    | Н                  |  |
| Bc-ss         | Bearbrook Clay - Sand Spot Phase       | POOR                | VERY SLOW           | 4                 | 3                    | M                  |  |
| Bsicl         | Bearbrook Silty Clay Loam              | POOR                | VERY SLOW           | 3                 | 4                    | Н                  |  |
| Bsil          | Bainsville Silt Loam                   | POOR                | SLOW                | 3                 | 3                    | Н                  |  |
| Cfsl          | Castor Fine Sandy Loam                 | IMPERFECT           | SLOW                | 3                 | 4                    | M                  |  |
| Cfsl-sh       | Castor Fine Sandy Loam - Shallow Phase | IMPERFECT           | MODERATE            | 2                 | 4                    | M                  |  |
| Er            | Eroded Channels                        | -                   | -                   | -                 | -                    | -                  |  |
| Fl            | Farmington Loam                        | WELL                | MODERATE            | 1                 | 4                    | L                  |  |
| Gl            | Grenville Loam                         | WELL                | MODERATE            | 1                 | 3                    | L                  |  |
| Gl-sh         | Greville Loam - Shallow Phase          | WELL                | RAPID               | 1                 | 4                    | L                  |  |
| GI-st         | Grenville Loam - Stony Phase           | WELL                | MODERATE            | 1                 | 3                    | L                  |  |
| Kgsl          | Kars Gravelly sandy Loam               | WELL                | RAPID               | 4                 | 1                    | L                  |  |
| LI            | Lyons Loam                             | POOR                | SLOW                | 2                 | 3                    | Н                  |  |
| M             | Muck                                   | VERY POOR           | SLOW                | 3                 | 2                    | M                  |  |
| Mnfsl         | Mountain Fine Sandy Loam               | IMPERFECT           | SLOW                | 3                 | 4                    | M                  |  |
| Mtl           | Matilda Loam                           | IMPERFECT           | MODERATE            | 2                 | 3                    | M                  |  |
| Mtl-sh        | Matilda Loam - Shallow Phase           | IMPERFECT           | RAPID               | 2                 | 4                    | M                  |  |
| Mtl-st        | Matilda Loam - Stony Phase             | IMPERFECT           | MODERATE            | 2                 | 3                    | M                  |  |
| NGcl          | North Gower Clay Loam                  | POOR                | <b>VERY SLOW</b>    | 3                 | 4                    | Н                  |  |
| Р             | Peat                                   | VERY POOR           | SLOW                | 3                 | 2                    | M                  |  |
| Rfs           | Rubicon Fine Sand                      | IMPERFECT           | MODERATE            | 4                 | 2                    | M                  |  |
| Rfsl          | Rubicon Fine Sandy Loam                | IMPERFECT           | MODERATE            | 2                 | 3                    | M                  |  |
| Roc           | St. Roaslie Clay                       | POOR                | <b>VERY SLOW</b>    | 3                 | 3                    | Н                  |  |
| Sfs           | St. Samuel Fine Sand                   | POOR                | SLOW                | 4                 | 2                    | M                  |  |
| Ufs           | Uplands Fine Sand                      | WELL                | RAPID               | 4                 | 1                    | L                  |  |
| Ufsl          | Uplands Fine Sandy Loam                | WELL                | RAPID               | 4                 | 2                    | L                  |  |
| Wc            | Wendover Clay                          | IMPERFECT           | <b>VERY SLOW</b>    | 3                 | 4                    | L                  |  |
| Wc-ss         | Wendover Clay - Sand Spot Phase        | IMPERFECT           | <b>VERY SLOW</b>    | 3                 | 2                    | M                  |  |